

Vattenkvalitet i kommunen

Område:	Hedemora	Västerby/ Vikmanshyttan	Långshyttan	Garpenberg	Garpenbergs- gård	Stjärnsund	Smedby	Nordansjö	Vikbyn	Intrånget	Grådö
Analyser											
Bakt:	2011-12-06	2011-12-20	2011-12-20	2011-11-22	2011-11-22	2011-10-04	2011-10-04	2011-12-06	2011-11-01	2011-11-22	2011-11-01
Odlingsb. mikroorg. 22°C 3d	<1	<1	<1	3	<1	<1	4	1	2	2	<1
Langsamvaxande bakterier 7 d	<10	<10	<10	<10	<10	<10	<10	10	<10	<10	30
35°	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
E. coli	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
Kem:	2011-12-06	2011-09-22	2011-10-20	2011-11-29	2011-08-03	2011-10-04	2011-10-04	11-12-06	11-11-01	2011-08-03	2011-12-06
Lukt	ingen	ingen	ingen	ingen	ingen	ingen	ingen	ingen	ingen	ingen	ingen
Lukt, art	-	-	-	-	-	<5	-	-	-	-	-
Färg	<5	<5	7.5	<5	<5	-	<5	<5	<5	<5	<5
Turbiditet FNU	0,24	0.18	1.2	<0.1	0.15	0.1	<0.1	<0.1	<0.1	0.24	<0.1
Järn, Fe	<0.05	<0.05	0.07	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ammoniumkvave, NH4-N	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Ammonium, NH4	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Konduktivitet	41.5	35.8	18.7	32.8	28.6	15.5	39.4	34.2	28.2	17.8	28.4
			8.0 Mn		1.5 F	83 Alk					
pH	7.8	8	7.9	7.6	8.2	7.9	8.0	7.5	8.0	8.2	8.1
Temp via pH o konduktivitet	20.7	19.8	20	22.8	24.5	17.9	19	21.4	22	24.4	21.5